



WILLIAMS

MILTON ROY

P1000V SERIES PUMP REPAIR KITS

REPAIR KIT NO. - RK1000V400 (1)_ (2)

PART NUMBER	DESCRIPTION	QUANTITY
BR-223-90	BODY SEAL O-RING	1
CV202288	DISCHARGE CHECK VALVE	1
CV202298	SUCTION CHECK VALVE	1
MC102174	PISTON GUIDE RING	1
MC102245	MOTOR RETURN SPRING	1
MC400-02BR	PISTON U-CUP/BUNA N	1
PP202249-01 ⁽¹⁾	PISTON/PLUNGER ASSEMBLY	1
SS1000V-PE ⁽²⁾	PLUNGER SEAL SET	1

REPAIR KIT NO. - RK1000V600 (1)_ (2)

PART NUMBER	DESCRIPTION	QUANTITY
BR-223-90	BODY SEAL O-RING	1
CV202288	DISCHARGE CHECK VALVE	1
CV202298	SUCTION CHECK VALVE	1
MC102245	MOTOR RETURN SPRING	1
MC102260	PISTON GUIDE RING	1
MC600-02BR	PISTON U-CUP/BUNA N	1
PP202259-__ ^{(1)*}	PISTON/PLUNGER ASSEMBLY	1
SS1000V-__ ⁽²⁾	PLUNGER SEAL SET	1

SEAL KIT NO. - SK1000V400 (1)

PART NUMBER	DESCRIPTION	QUANTITY
BR-022	O-RING-BUNA N	1
BR-116	O-RING-BUNA N	1
BR-223-90	BODY SEAL O-RING	1
MC102174	PISTON GUIDE RING	1
MC400-02BR	PISTON U-CUP/BUNA N	1
SS1000V-PE ⁽²⁾	PLUNGER SEAL SET	1
PP302262-01 ⁽¹⁾	PISTON/PLUNGER ASSEMBLY	1
TT-112	O-RING/TEFLON	1
T-012	O-RING/TEFLON	1

SEAL KIT NO. - SK1000V600 (1)

PART NUMBER	DESCRIPTION	QUANTITY
BR-022	O-RING-BUNA N	1
BR-116	O-RING-BUNA N	1
BR-223-90	BODY SEAL O-RING	1
MC102260	PISTON GUIDE RING	1
MC600-02BR	PISTON U-CUP/BUNA N	1
SS1000V-PE ⁽²⁾	PLUNGER SEAL SET	1
TT-112	O-RING	1
T-012	O-RING	1

(1) & (2): To order the proper plunger and seal materials, please indicate the appropriate letter as shown in the example below. The letters following the dash for the piston plunger assembly (PP202249) and plunger seal set (SS1000V) will correspond to the material chosen in the repair kit number.

